BILLY PUGH COMPANY

5878 Agnes Street, Corpus Christi, Texas 78406, USA
P.O. Box 802, Corpus Christi, Texas 78403
+1 361.884.9351 · bpc@billypugh.com · www.billypugh.com

WORK VEST DONNING INSTRUCTIONS

WVO-50 and WVO-100 USCG approved Type V work vests · BPC-MAN-WVO

TIER 3 · OPERATING INSTRUCTIONS

Document no.	BPC-MAN-WVO	**Revision**	Rev. 0
Issue date	28-OCT-2026	**Status**	Controlled document
Document owner	Quality & Safety Coordinator	**Approved by**	Chief Operating Officer

How to put on the Billy Pugh WVO-50 and WVO-100 work vests. Read and follow the information printed on the vest and its label.

1. DONNING

1. Put on the work vest.

2. Buckle the top and bottom chest straps.

3. Adjust the side strap for a snug fit.

BILLY PUGH COMPANY

5878 Agnes Street, Corpus Christi, Texas 78406, USA
P.O. Box 802, Corpus Christi, Texas 78403
+1 361.884.9351 · bpc@billypugh.com · www.billypugh.com

4. Adjust the shoulder straps for a snug fit.

2. REVISION HISTORY

Rev.	Date	Description of change	Issued by
0	28-OCT-2026	First issue under a controlled document number. Source: uncontrolled single-page "USCG Approved Type V Work Vest Donning Instructions, Model WVO-50 & WVO-100" (Rev 0) published on billypugh.com, which carried the former "Billy Pugh Co., Inc." name and logo. Steps and photographs unchanged.	R. Siqueira, CEO

3. APPROVAL

	Name and title	Signature	Date
Prepared by	Rodrigo Siqueira, Chief Executive Officer		28-OCT-2026
Approved by	Ray Coleman, Chief Operating Officer		